

Project No: MCC001901030201

Project: Final Remedial Investigation

Client: AFCEE

Location: Site 24 - Vandenberg AFB

Northing: 640279.649

Borehole ID: HGL40(24MW16B)

Date: 12/9/2002

Geologist: P. Sullivan Checked By: D. Smith, R.G.

Ground Surface Elevation(ft msl): 458.94

Easting: 1768198.113

SUBSURFACE PROFILE					SAMPLE				
Depth	Symbol	Description	nscs	Elevation	Recovery %	Blow Counts	PID (ppm)	Water Level	Remarks
111	XX	Fill	fill						
2									
4-	▓								Lock (FLC FI) as a set of
6-				452	100	7/8/8	1.8		Lost (5'-6.5') sample due to blocked sampler.
8-		Sand with silt	SM						
10=		Pale yellowish brown (70%) mottled with dark yellowish orange (30%), medium		449	60	24/50 5 48	0.4		
12-		dense, moist, 90% medium grained /sand, 10% silt	SP		-00	34/50 for 1"	2.4		
]		Poorly graded sand							
14-		Pale yellowish brown, medium dense,			· 				
16-		moist, 100% medium grained sand soft at 15'			-70	15/30/36	2.1	<u> </u> 	
18									
20-					60	39/40/50 for 5"	1.3		
22-									ľ
24				-					
26					100	30/34/40	1.3		
]					100	30/34/40	1.3		·
28-		unit becomes 1000/ fire analysis of any last						:	
30		unit becomes 100% fine grained sand at 30'			50	44/50 for 5"	2.0		·
32	72	Sand with clay	SC	427					
34-		Dark yellowish orange, dense, moist,	SP	425					
36-		85% medium grained sand, 15% clay			80	27/40/50 for 3"	2.2		
<u> </u>		Poorly graded sand Pale yellowish brown, very moist, soft,							
38-		100% medium grained sand		419				Ŧ	Set temporary well at 40'.
40-	//			713	90	20/33/50 for 5"	1.8		

Drilled By: Layne Christensen

HydroGeoLogic, Inc.

Drill Method: Dual Tube Percussion

4600 Northgate Blvd., Suite 207 Sacramento, CA 95834

Drilling Equipment: AP-1000

(916) 614-8770 FAX (916) 614-8775

Boring Diameter: 10"

Total Depth Drilled: 76'

Sheet: 1 of 2

Sampling Equipment: CA Mod Split Spoon



Project No: MCC001901030201

Project: Final Remedial Investigation

Client: AFCEE

Location: Site 24 - Vandenberg AFB

Northing: 640279.649

Borehole ID: HGL40(24MW16B)

Date: 12/9/2002

Geologist: P. Sullivan
Checked By: D. Smith, R.G.

Ground Surface Elevation(ft msl): 458.94

Easting: 1768198.113

SUBSURFACE PROFILE						SAMPLE			
Depth	Symbol	Description	nscs	Elevation	Recovery %	Blow Counts	PłD (ppm)	Water Level	Remarks
42		Sand with clay Pale yellowish brown mottled with light brown, moist, hard, 85% medium grained sand, 15% clay	SC SP	417	90				
46 48		Poorly graded sand Pale yellowish brown, very moist, soft, 100% fine grained sand			70	27/35/50 for 3"	2.1		
50 52					50	26/50 for 5"	0.4		
54-							···		
56 58		lense of sand with clay from 55.5' to 56.5'	SC SP		100	19/23/50 for 5"	0.9		
60		unit becomes moist and 100% medium grained sand at 56.5'			70	18/30/50 for 4"	2.5		
62-		unit becomes 100% medium grained sand at 60'						¥	
66		unit becomes saturated and 100% coarse sand at 65'			100	10/20/27	2.7	. =	,
70									
72- 74-				383					Set temporary well at 76'.
76 78 80	20167412	Clay Olive gray, stiff, low plasticity, moist, 90% clay, 10% silt	CL	300	·				Boring converted to deep well 24MW16B.

Drilled By: Layne Christensen

HydroGeoLogic, Inc.

Drill Method: Dual Tube Percussion

4600 Northgate Blvd., Suite 207 Sacramento, CA 95834

Drilling Equipment: AP-1000

(916) 614-8770 FAX: (916) 614-8775

Sampling Equipment: CA Mod Split Spoon

Boring Diameter: 10"

Total Depth Drilled: 76'

Sheet: 2 of 2